

ROBERT P. BEEBE

Naval Architect

BOX 1452, CARMEL, CALIFORNIA 93921 • TELEPHONE 408-624-8410

2 November 1981

Dear Mr. Jurgens:


In regard to the "Lloyds Certificate" PM was not built under full Lloyds supervision that would result in a rating. They had then (I dont know about now) a lesser program that inspected the timber and supervised the machinery installation. I do not find in my files any reference to this, if it is not on PM then I dont know where it would be.

Actually, I considered this a waste of money except for the initial timber inspection as it worked out I was there from the framing to the end and did all the inspecting myself that was needed.

I'm sending you the print from my plan file from which the rig was actually built. If I have any reason to want another I can get it printed from the original tracings if I work it over. Pencil plans seem to dim with time, Farmer told me the graphite evaporates.

Best of luck on your cruise.

Very truly yours,

  
Robert P. Beebe